

NOTE: The C7215 Module does *not* automatically implement a Safety Circuit in the C7160-3 Control; or a Threshold Scan Circuit in the C2160-1 Control. Additional modules are available for those control / function combinations.

Horton Automatics
4242 Baldwin Blvd.
Corpus Christi, Texas 78405
(361) 888 - 5591 1-800-531-3111
Fax No. 1-361-888-6510

C7215 SIMULTANEOUS ACTUATION MODULE TYPICAL WIRING

11014.0

MAY'91